



Factory gate



Factory name



BSCI code posted onsite



Production building



Office building



Raw material area



Printing



Extruding forming



Pasting



Cutting, Sewing and packing



Finished goods warehouse



Emergency light and exit sign, evacuation plan



Fire extinguishers



Firefighting facilities



Toilet



Fire alarm test



Emergency light test



Fire hydrant test



Chemical stored area



Eye washing facility



Potable water



Proper PPE was provided



Suggestion box



Attendance recorder



First aid kit



Dormitory building



Kitchen



Canteen



Bedroom



Bathroom and toilet in dormitory



Exit sign and emergency light in dormitory



Fire hydrant in dormitory



Evacuation plan in dormitory



Fire extinguishers in dormitory



NC: Goods were stacked against the wall



NC: No PPE of worker.

Factory name: DONGGUAN
COMMODITY CO.,LTD.
Site amfori ID: 156-025824-001

FAVORHOME **Report No.:** JSASCN24272576
Audit Date: Dec 18, 2024
Page 7 of 7



NC: No needle guard was installed of over lock sewing machine.



NC: No needle guard or finger guard installed of one sewing machine.

----- END -----